

Late of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

October 13, 2005

Supervisor ARA

Mine Name: Topaz Valley Limestone Operator Name: Rancho Equipment

Robert Thomas

1557 West Ashby Road Delta, Utah 84624-7357 Inspector(s): Tom Munson Other Participants: none

Mine Status: regraded and seeded

Permit number: M023/022 Inspection Date: 09/29/2005 Time: 10:30-11:30AM

Weather: Sunny

	Elements of Inspection	Evaluated	Comment	Enforcement
1. P	ermits, Revisions, Transfer, Bonds	\boxtimes		
2. P	ublic Safety (shafts, adits, trash, signs, highwalls)			
3. P	rotection of Drainages / Erosion Control			
1. D	eleterious Material			
5. R	oads (maintenance, surfacing, dust control, safety)			
	oncurrent Reclamation			
7. B	ackfilling/Grading (trenches, pits, roads,		a F	
h	nighwalls, shafts, drill holes)	Ц		
3. W	Vater Impoundments			
). Se	oils			
0. 1	Revegetation			
1. 1	Air Quality			
2. (Other			П

Purpose of Inspection: To evaluate the revegetation success at this reclaimed site.

Directions to Site:

Turn on the Brush Wellman mine road north of Delta and turn again at the Topaz Valley Amphitheatre Road and take your next left, drive 1 mile and it is on your right.

Inspection Summary:

I arrived on site and walked the entire site to survey the amount of vegetation. It was determined that the site is doing a lot better after this year of normal precipitation. There was evidence of crested wheat grass, rice grass, forage koshia, four wing salt brush, shad scale, tumble weed, halogeton, and cheat grass.

Conclusions and Recommendations:

The site was last inspected and photo documented on 02/24/2005 and before this 5/5/2003. As can be observed in the attached photos during the 02/24/2005, the site was mainly covered with halogeton and some forage koshia. The site had no vegetation on 05/05/2003 and had been seeded three times since the fall of 2000.



Inspection Date: 09/29/2005; Report Date: 10/13/2005

Page 2 of 2 M/023/022

A soil sample was analyzed in the summer of 2003 and it was determined that the operator had basically over fertilized the site and due to the drought the soil salinity was keeping anything from growing. It was determined that time would be the best solution to a very difficult problem of getting the vegetation to become established. Fortunately, time has been favorable to the site and now that five years have passed since the first seeding, the site has appeared to turn the corner and could possibly be released.

Date: October 13, 2005

Inspector's Signature


tm:jb

cc: Robert Thomas, Operator

Jerry Mansfield, Fillmore BLM

Attachment: Photos

O:\M023-Juab\M0230022-Topazvalley-Rancho\inspections\ins-09282005.doc






INSPECTION09282005 021.JPG 2005/09/29 10:48:48 WHEAT 6 RASS




INSPECTION09282005 022.JPG 2005/09/29 10:49:25



INSPECTION09282005 023.JPG 2005/09/29 10:49:35




INSPECTION09282005 024.JPG 2005/09/29 10:49:47






INSPECTION09282005 019.JPG 2005/09/29 10:44:18



INSPECTION09282005 018.JPG 2005/09/29 10:42:08





ECTION09282005 009.JPG 2005/09/29 10:35:08




INSPECTION09282005 011.JPG 2005/09/29 10:37:10




INSPECTION09282005 010.JPG 2005/09/29 10:37:04








INSPECTION09282005 014.JPG 2005/09/29 10:39:59




INSPECTION09282005 015.JPG 2005/09/29 10:40:17




INSPECTION09282005 016.JPG 2005/09/29 10:40:22




INSPECTION09282005 007.JPG 2005/09/29 10:34:50







INSPECTION09282005 001.JPG 2005/09/29 10:32:50




INSPECTION09282005 003.JPG 2005/09/29 10:33:04



INSPECTION09282005 002.JPG 2005/09/29 10:32:59




INSPECTION09282005 004.JPG 2005/09/29 10:33:09



INSPECTION09282005 025.JPG 2005/09/29 10:53:50



INSPECTION09282005 027.JPG 2005/09/29 10:55:45



INSPECTION09282005 026.JPG 2005/09/29 10:53:53

